

TECHNICAL SPECIFICATIONS

| Feature | Unit | Minimum limit | Standard | Maximum limit |
|---------------|----------------------|---------------|----------|---------------|
| Grams/meter | g/sq.m | 450 | 500 | 550 |
| Width | inches | 49 | 51 | *** |
| Cutable width | inches | 47 | 49 | *** |
| Fabric Yield | m/kg | 1.33 | 1.54 | 1.80 |
| Ounces/yards | Oz/sq.yd | 13.3 | 14.8 | 16.2 |
| Fiber content | 95% NYLON 5% SPANDEX | | | |

Certifications



Additional comments about technical specifications

Larger width is not considered to be out of specification.

REST TIME 24 HOURS.

Style subject to light folding marks.

Style subject to crease marks.

Style may contain barre.

NCM

| PFD | Off White/White | Dyed | Printed |
|------------|-----------------|------------|------------|
| 6004.10.31 | 6004.10.31 | 6004.10.32 | 6004.10.34 |

DIMENSIONAL STABILITY

| Shrinkage after washing (Hand wash - hang to dry %) | Length (%) | Width (%) |
|---|------------|-----------|
| | 5 | 3 |

Additional comments about dimensional stability

The shrinkage value is an average between the batches produced and may be subject to change.

Do not leave dirty clothes together in a closed place for a long time, always keep separated in a cool and ventilated place. Separate by light and dark colors. Use neutral soap. Do not twist.

WASHING INSTRUCTIONS



- hand wash




- do not bleach



- hang to dry



- maximum temperature for the iron heat 110C (230F)



- do not dryclean

Note - The symbols should appear in the following order: washing, bleaching, drying, ironing and professional dry cleaning.

Additional instructions to use with care symbols

- Do not tumble dry.
- No steam.
- Do not wring.

STORAGE INSTRUCTIONS

- Do not hit the ends of the fabric (do not hit the top).
- Keep the packaging of the rolls until their end use.
- The identification of the rolls must always be kept.
- Stored textiles should not be exposed to the light. The exposure will compromise the fabric over time.
- Separate by batch.

GENERAL COMMENTS

- Neon colors have low resistance to light and washing; they should not be mixed with other colors and / or fabric in the same piece; they should be washed separately.
- The washing mode is performed on the fabric, but after the fabric is converted into clothing, it must be evaluated (clothing appearance, use of other fabrics, use of interfacing / interlinings, etc).
- Be careful of the fabric getting in contact with abrasive surfaces, yarn may be tugged.
- Do not mix batches.
- Claims will be accepted within 15 days after receipt of the goods.
- All tests mentioned above were performed through NBR, ISO, AATCC standards and / or internal standards.

Prepared by Sara Almeida: Quality / Kalimo
Approved by Murilo Garcia: Technical Manager