

TECHNICAL SPECIFICATIONS

| Feature | Unit | Minimum limit | Standard | Maximum limit |
|---------------|-----------------------|---------------|----------|---------------|
| Grams/meter | g/sq.m | 243 | 270 | 297 |
| Width | inches | 43 | 45 | *** |
| Cutable width | inches | 41 | 43 | *** |
| Fabric Yield | m/kg | 2.79 | 3.22 | 3.77 |
| Ounces/yards | Oz/sq.yd | 7.2 | 8.0 | 8.8 |
| Fiber content | 89% NYLON 11% SPANDEX | | | |

Certifications



Additional comments about technical specifications

Larger width is not considered to be out of specification.

REST TIME 24 HOURS.

NCM

| PFD | Off White/White | Dyed | Printed |
|------------|-----------------|------------|------------|
| 6004.10.31 | 6004.10.31 | 6004.10.32 | 6004.10.34 |

DIMENSIONAL STABILITY

| Shrinkage after washing (Hand wash - hang to dry %) | Length (%) | Width (%) |
|---|------------|-----------|
| | 6 | 12 |

Additional comments about dimensional stability

The shrinkage value is an average between the batches produced and may be subject to change.

Do not leave dirty clothes together in a closed place for a long time, always keep separated in a cool and ventilated place. Separate by light and dark colors. Use neutral soap. Do not twist.

WASHING INSTRUCTIONS



- hand wash



- do not bleach



- hang to dry



- do not iron



- do not dryclean

Note - The symbols should appear in the following order: washing, bleaching, drying, ironing and professional dry cleaning.

Additional instructions to use with care symbols

- Do not wring.

STORAGE INSTRUCTIONS

- Do not hit the ends of the fabric (do not hit the top).
- Keep the packaging of the rolls until their end use.
- The identification of the rolls must always be kept.
- Stored textiles should not be exposed to the light. The exposure will compromise the fabric over time.
- Separate by batch.

GENERAL COMMENTS

- Neon colors have low resistance to light and washing; they should not be mixed with other colors and / or fabric in the same piece; they should be washed separately.
- The washing mode is performed on the fabric, but after the fabric is converted into clothing, it must be evaluated (clothing appearance, use of other fabrics, use of interfacing / interlinings, etc).
- Be careful of the fabric getting in contact with abrasive surfaces, yarn may be tugged.
- Do not mix batches.
- Claims will be accepted within 15 days after receipt of the goods.
- All tests mentioned above were performed through NBR, ISO, AATCC standards and / or internal standards.

Prepared by Sara Almeida: Quality / Kalimo
Approved by Murilo Garcia: Technical Manager